## Division of Enforcement & Compliance Assistance - Air Compliance Branch (DECA-ACB) 290 Broadway-21<sup>5t</sup> Floor New York, NY 10007-1866 NOTIFICATION OF DEMOLITION AND RENOVATION ect # Postmark Date Received

Operator Project #	Postmark	. DEMOE		eceived		Notification	
	01.02.8		8.30.1	0	316	381	
I. TYPE OF NOTIFICATION (O		_					
II. FACILITY INFORMATION ( Identify owner, removal contractor, and other operator)							
OWNER: Westchester Medical Cen	ter	*			20042	1	
Address: 95 Grasslands Road		900					
City:Valhalla			State: New Yor	k	ZIP: 1059	5	
Contact: Michael Praskievicz					Tel: 914-4	93-7912	
REMOVAL CONTRACTOR: JVN F	Restoration Inc.						
Address: 47 Foster Road						1000000 \$ 00000 \$	
City: Staten Island	y: Staten Island Sta		State: New Yo	State: New York		ZIP: 10309	
Contact: John Tardy	2.47 (2				Tel: 718-6	Tel: 718-605-6256	
		-					
Address:	THE STATE OF THE S		17-2-180-181-1-1-1				
OTHER OPERATOR:	7-2-11					Special de Royal Control	
Contact:					Tel:		
III. TYPE OF OPERATION ( D = D	emolition / R = Renovation	on) : R / As	bestos Removal	Only			
IV. IS ASBESTOS PRESENT? (Y	es/ <u>N</u> o): yes		n (				
V FACILITY DESCRIPTION (i	nclude building name,	number ar	nd floor or room	number): Macy	s Pavillion		
Building: Westchester Medical Cent	ter						
Address: 95 Grasslands Road							
Address:					***	Company of the same of the sam	
City Valhalla	# 10 m		State: New Yo	ork	County: W	/estchester	
Site Location: Westchester Medical	Center						
Building Size	SqMeter:	SqFt:		# of Floors:		Age in Years	
Present Use: Hospital		100000		Drior Use: Hos	nital	50+	
Present Use: Hospital  VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Bulk/PLM							
OF ASBESTOS MATERIAL:	Bulk/PLM (AHERA)	FAFFROF	RIATE, USED TO	DETECTINE	PRESENCE		
VII. APPROXIMATE OF RACM TO SPECIFY THE AMOUNT OF ASB	BE REMOVED AND NO	ON-FRIABI	E ASBESTOS N	ATERIAL THA	T WILL NOT B	E REMOVED.	
of Edit File Allookt of Adb	ESTOS BELOW.		RACM to be Re		on-friable Asbo not to be re Category I		
PIPES - Linear Feet	60 A C C C C C C C C C C C C C C C C C C						
PIPES- Linear Meters							
Surface Area - Square Feet			700				
Surface Area - Square Meters							
Volume RACM off Facility Component - Cubic Feet							
Volume RACM off Facility Component - Cubic Meters							
xVIII. SCHEDULED DATES OF ASBESTOS REMOVAL: (MM/DD/YY) Start: 9/8/2010 Completion:12/31/2010							
X. SCHEDULED DATES OF DEMOLITION/RENOVATION: (MM/DD/YY) Start: Completion:							

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVA' N/A	TION WORK, AND MET	THOD(S) TO BE USED:				
XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING COL ASBESTOS AT THE DEMOLITION AND RENOVATION SITE: Negative air machines under HEPA filtration system. Wet Metl	NTROLS TO BE USED hods.	TO PREVENT EMISSIONS OF				
XII. WASTE TRANSPORTER #1						
Name: Express Waste Services		TO THE STATE OF TH				
Address: 614 Frelinghuysen Avenue		<u> </u>				
City: Newark	State: New Jersey	ZIP: 07114				
Contact Person:		Telephone:				
WASTE TRANSPORTER #2						
Name:						
Address:						
City:	State:	ZIP:				
Contact Person:						
XIII. WASTE DISPOSAL SITE						
Name: Cumberland County Landfill						
Address:		and the second s				
City: Newburg	State: PA	ZIP: 17242				
Telephone: 717 423-5917	Otate. 1 A	211 . 17272				
XIV. IF DEMOLITION IS ORDERED BY A GOVERNMENT AGENCY,	DI EASE IDENTIFY TH	IE AGENCY BELOW				
	Title:	IL ACERO! DELOW				
Authority:	Tiue.					
	Date Ordered to Penin	(MM/DD/VV)				
	Date Ordered to Begin (MM/DD/YY) :					
XV. FOR EMERGENCY RENOVATIONS						
Date and Hour of Emergency (MM/DD/YY):		100 CO 10				
Description of the Sudden, Unexpected Event:						
Explanation of How the Event caused Unsafe Conditions or Seriou	s Disruption of Indust	rial Operation:				
XVI. DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE E PREVIOUSLY NON-FRIABLE ASBESTOS BECOMES CRUMBLEI	VENT THAT UNEXPEC D, PULVERIZED, OR R	TED ASBESTOS IS FOUND OR REDUCED TO POWDER:				
XVII. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIO SUBPART M) WILL BE ON-SITE DURING THE DEMOL REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY INSPECTION DURING NORMAL BUSINESS HOURS. (  John Tardy	ITION OR RENOVATION THIS PERSON WILL E	ON AND EVIDENCE THAT THE BE AVAILABLE FOR Dromulgation) .				
Signature of Owner/Operator Project Manager  XVIII. / I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT  John Tardy	8/27/201	Date				
Signature of Owner/Operator Project Manager	6/2//201	Date				
- Jane						